

Inspection Photos
Operator: Simcoe
API: 067-09187
Date: 2/18/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Multiple soil piles are placed along the western edge need to be stabilized with desirable vegetation.




Photo 3. View of wire debris observed within the western project area.



Photo 4. View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 5. View of reference area vegetation comprised of open grass fields mixed with scattered sagebrush, rubber rabbitbrush, and pinyon and juniper trees.