

Inspection Photos  
Operator: Simcoe  
API: 067-08662  
Date: 2/18/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Location largely snow covered, perennial vegetation observable through snow needs to be assessed during the active growing season.



Photo 3. View of the southern project area from the southeastern corner facing northward.



Photo 4. View of reference area vegetation comprised of open grass fields mixed with scattered sagebrush, rubber rabbitbrush, and pinyon and juniper trees.