

Inspection Photos
Location Name: Judy 4N64W6W Tank Battery
Facility ID: 481585



Photo #1 Location



Inspection Photos
Location Name: Judy 4N64W6W Tank Battery
Facility ID: 481585



Photo #2 Bird Protector installed




Photo #3 Unused Equipment was not removed

