

Inspection Photos
Location Name: Hahn 1-14H
Location ID: 424891



Photo 1 – Tank Battery



Photo 2 – Heater Treater

Inspection Photos
Location Name: Hahn 1-14H
Location ID: 424891



Photo 3 – Tank Battery Sign



Photo 4 – ECD

Inspection Photos
Location Name: Hahn 1-14H
Location ID: 424891



Photo 5 – Flare



Photo 6 – Stained Soil at Exhaust

Inspection Photos
Location Name: Hahn 1-14H
Location ID: 424891



Photo 7 – Wellhead



Photo 8 – Pumping Unit