



<b>Inspected Facilities</b>			
Facility ID: <u>457362</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u> Insp. Status: <u>AC</u>
<b>Producing Well</b>			
Comment:	AC (location is partially set up for mill out operations on completed wells, however, no milling unit is on location at time of inspection. Flowback equipment appears to be on standby).		
Corrective Action:		Date:	
<b>Complaint</b>			
Comment:	<p>18#402959831 Inspection DOC # 694400395</p> <p>Inspection in response to complaint. Inspector: Adam Kraich Location # 478497 Location Name: Knight Pad Nature of complaint: Noise 2/18/2022-I received a complaint concerning low frequency noise suspected to be coming from the Knight location. On 2/18/2022, COGCC Staff deployed a continuous sound meter at the complainants address approximately 25' from the complainants home, as guided by COGCC rule 423 c.(2) A. The study ran over the weekend and concluded on 2/22/2022. Adjustments are made to the study that eliminate weather exemptions (wind speeds in excess of 5mph). LEQ 2 is calibrated for low frequency (C-scale). The overall observed LEQ-2 for the entirety of the study is observed at 69.4 DB. When nighttime operations (19:00-07:00HOURS) are isolated the average LEQ 2 is observed at 67.3 DB. And daytime isolation is observed at 67.5DB. Indicating non compliance under COGCC rule 423-1 (2) B. "Baseline" sound monitoring was conducted on 2/10/2022 through 2/14/2022. To which, Cub Creek voluntarily shut all operations down, and shut in the facility to run a baseline sound audit. The results of the audit were observed at 59.5 (adjusted for weather considerations) over the time of the shut in.</p> <p>See attachemnts for sound audit and weather details.</p> <p><b>END OF REPORT.</b></p>		
Corrective Action:	Comply with rule 423-1 (2) B.		Date: <u>02/25/2022</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694400396	Baseline audit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671813">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671813</a>
694400397	Baseline Day time Audit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671814</a>
694400398	Day time sound audit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671815">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671815</a>
694400399	Baseline audit weather data	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671816">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671816</a>
694400400	Night time sound audit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671817</a>
694400401	weather data	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671818">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671818</a>