

Inspection Photos

API: 071-08049

Operator: OGRIS OPERATING LLC

Inspection Date: 2/22/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08049 | Date: 2/22/2022

Inspection Photos



Photo 1. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08049 | Date: 2/22/2022

Inspection Photos



Photo 3. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08049 | Date: 2/22/2022

Inspection Photos



Photo 3. There is some oily rags and fluids on the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08049 | Date: 2/22/2022