

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2022

Submitted Date:

02/23/2022

Document Number:

699602781**FIELD INSPECTION FORM**

Loc ID 420292	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 14 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>1001 NOBLE ENERGY WAY</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77070</u>				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481646	TANK BATTERY	AC	02/18/2022		-	Bashor PC AA 09-14 Tank Battery	IO

General Comment:

This is a TANK BATTERY inspection.
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID (481646).
Centralized Battery serves 3 Location IDs (309821, 309868, 420225).
(Well(s): 3: Temporarily Abandoned | TA).
Centralized Battery formerly served 1 Location ID (420208).
(Well(s): 1: Plugged & Abandoned | PA).

-Refer to Field Inspection Report doc. #699602783 and/or Location ID #309821 for Well(s) info.
Well(s): 1: Temporarily Abandoned | TA.
-Refer to Field Inspection Report doc. #699602785 and/or Location ID #309868 for Well(s) info.
Well(s): 1: Temporarily Abandoned | TA.
-Refer to Field Inspection Report doc. #699602787 and/or Location ID #420225 for Well(s) info.
Well(s): 1: Temporarily Abandoned | TA.
-Refer to Field Inspection Report doc. #699602789 and/or Location ID #420208 for Well(s) info.
Well(s): 1: Plugged & Abandoned | PA.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Barbed wire. Surrounded by earth berms.			
Corrective Action:				Date:
Type	IGNITOR/COMBUSTOR			
Comment:	Barbed wire.			
Corrective Action:				Date:
Equipment:				
Type: Pig Station	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:	1: Gas Sales. Calibration card indicates calibration within last year. Last calibration: 09/14/2021. Inactive, no production. 2: Gas Sales. NO Calibration card. Meter removed. Inactive, no production.			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			

Comment: ECD scrubbers.		Date:
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment: 1: Crude storage vapor line combustor. Controls crude oil tank vapors. Pilots: OFF. Shut-down. 1: Separator vapor line combustor. Controls separator vapors. Pilots: OFF. Shut-down.		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:		Centralized Battery serves 1 Tank Battery Facility ID (481646). Centralized Battery serves 3 Location IDs (309821, 309868, 420225).			
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	75 Bbls.
Other (Type)	

Berms

Inspector Name: Evins, Bret

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:		Shares berms w/ crude oil tanks & produced H2O vault.			
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)		53 Bbls.			
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:		Shares berms w/ crude oil tanks & produced H2O tank.			
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.499408,-104.444969
Comment:		Equalizer line connects crude oil tanks.			
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:		Shares berms w/ produced H2O tank, vault.			
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 02/16/2022 at approximately 14:23 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Bashor PC AA 09-14 Tank Battery / Facility ID: 481646 Well Name(s): Bashor 9-43, Bashor 9-42, Bashor PC AA 09-14, Bashor PC AA 09-24. API: 05-123-25425, 05-123-25491, 0123-05-32508, 05-123-32509. Location County: Weld County, Colorado Weather: Overcast, w/ light snow falling & snow from prior storm.</p> <p>While there, I observed: Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481646). Centralized Battery serves 3 Location IDs (309821, 309868, 420225). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery formerly served 1 Location ID (420208). (Well(s): 1: Plugged & Abandoned PA).</p> <p>-Refer to Field Inspection Report doc. #699602783 and/or Location ID #309821 for Well(s) info. Well(s): 1: Temporarily Abandoned TA. -Refer to Field Inspection Report doc. #699602785 and/or Location ID #309868 for Well(s) info. Well(s): 1: Temporarily Abandoned TA. -Refer to Field Inspection Report doc. #699602787 and/or Location ID #420225 for Well(s) info. Well(s): 1: Temporarily Abandoned TA. -Refer to Field Inspection Report doc. #699602789 and/or Location ID #420208 for Well(s) info. Well(s): 1: Plugged & Abandoned PA.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/23/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699602782	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5672421