

Inspection Photos
Location Name: BASHOR PC AA /09-23
Location #: 420598



Photo #1

Bashor PC AA 09-23 (05-123-32644) Wellsite
Temporarily Abandoned | TA



Photo #2

Bashor PC AA 09-08 Tank Battery
Battery site
Inactive / Shut-down
Equipment documented Fac. ID 481647
Formerly served:
Bashor PC AA 09-22; Plugged & Abandoned | PA