

Inspection Photos

Location Name: 70 RANCH USX BB /09-99HZ

Location #: 420599



Photo #1

Bashor PC AA 09-22 (05-123-32643) Wellsite

Plugged & Abandoned | PA

~ 25 yds.

Cut / Capped



Photo #2

Bashor PC AA 09-08 Tank Battery

Battery site

Inactive / Shut-down

Equipment documented Fac. ID 481647

Formerly served:

Bashor PC AA 09-22; Plugged & Abandoned | PA