

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/16/2022

Submitted Date:

02/23/2022

Document Number:

699602793

**FIELD INSPECTION FORM**

Loc ID 420596	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 17 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC Address: 1001 NOBLE ENERGY WAY City: HOUSTON State: TX Zip: 77070				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420595	WELL	TA	03/11/2020	OW	123-32642	BASHOR PC AA 09-08	TA

**General Comment:**

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID (481647).

Centralized Battery serves 2 Location IDs (420596, 420598).

(Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery formerly served 1 Location ID (420599).

(Well(s): 1: Plugged &amp; Abandoned | PA).

Refer to Field Inspection Report doc. #699602791 and/or Facility ID #481647 for Battery / Facility, Equipment info.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Equipment now assigned to Tank Battery Facility ID #481647.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Equipment now assigned to Tank Battery Facility ID #481647.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Equipment now assigned to Tank Battery Facility ID #481647.		
Corrective Action:		Date:	

Type: Plunger Lift	# 0	
Comment:	Temporarily Abandoned   TA. Equipment removed.	
Corrective Action:		Date:
Type: Ancillary equipment	# 0	
Comment:	Equipment now assigned to Tank Battery Facility ID #481647.	
Corrective Action:		Date:
Type: Pig Station	# 0	
Comment:	Equipment now assigned to Tank Battery Facility ID #481647.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.504389,-104.432704
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (481647). Centralized Battery serves 2 Location IDs (420596, 420598). Refer to Field Inspection Report doc. #699602791 and/or Facility ID #481647 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Equipment now assigned to Tank Battery Facility ID #481647.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment: Equipment now assigned to Tank Battery Facility ID #481647.						
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 420595 Type: WELL API Number: 123-32642 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Well disconnected from flowline.  
Locked-Out, Tagged-Out | LOTO.  
Blue TA tag posted.  
COGCC records last production: 10/2018.  
  
Form 4 Sundry on file. TA date: 02/06/2020.  
Approved.  
  
Form 21-MIT on file. MIT date: 02/07/2020.  
Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 03/16/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 02/16/2022 at approximately 13:25 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: BASHOR PC AA /09-08  Location ID: 420596  Well Name(s):  Bashor PC AA 09-08.  API: 05-123-32642.  Location County: Weld County, Colorado  Weather: Overcast, w/ light snow falling &amp; snow from prior storm.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481647).  Centralized Battery serves 2 Location IDs (420596, 420598).  (Well(s): 2: Temporarily Abandoned   TA).  Centralized Battery formerly served 1 Location ID (420599).  (Well(s): 1: Plugged &amp; Abandoned   PA).</p> <p>Refer to Field Inspection Report doc. #699602791 and/or Facility ID #481647 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/23/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699602794	Site photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5672631">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5672631</a>