

Final Reclamation Inspection

February 15, 2022

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 317498

Inspection Document #: 697503732

Weld County, CO

SWNW Section 14 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: APRIL #12-14
Location ID: 317498



Photo 1. Drone aerial imagery illustrates the April #12-14 location. The photo illustrates the Operator has failed to complete final reclamation activities for the well location portion of the location (red polygon).

Inspection Photos
Location Name: APRIL #12-14
Location ID: 317498



Photo 2. Operator is in process of closing 3 of the 4 pits per 900 series rules. Upon receiving final approval to close the pits, Operator shall further reduce the size of the location by returning 2 of the 3 pits back into crop production (red polygon).

Inspection Photos
Location Name: APRIL #12-14
Location ID: 317498



Photo 3. Photo taken from the wellhead. Photo illustrates Operator has not removed gravel and debris and recontoured the well location portion of the location.

Inspection Photos
Location Name: APRIL #12-14
Location ID: 317498



Photo 4. Photo taken from location, facing South. Photo illustrates poor “good housekeeping”. Note- COGCC Staff put the barrel upright, as there appear to be some liquid remaining inside the barrel.



Photo 5. Photo taken west of the pits, facing East. Photo illustrates poor “good housekeeping”.

Inspection Photos
Location Name: APRIL #12-14
Location ID: 317498



Photo 6. Photo taken from the separator, facing North. Photo illustrates poor “good housekeeping”.



Photo 7. Photo taken from the northern location, facing North. Photo illustrates potentially unused equipment.