

Inspection Photos
Location Name: ROHR USX A /28-25
Location #: 420803



Photo #1
Rohr A 28-25 (05-123-32718) Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Intermediate plugs cementing



Photo #2
Rohr A 28-25 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
*Site safety signage
prior photo*

Inspection Photos
Location Name: ROHR USX A /28-25
Location #: 420803



Photo #3
Rohr A 28-25 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Battery sign
prior photo