

Final Reclamation Inspection

December 15th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322607

Inspection Document #: 701900340

SENW Section 13 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: R. Andersen Unit 1-13
Location ID: 322607



Photo 1. 2021 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos
Location Name: R. Andersen Unit 1-13
Location ID: 336478



Photo 2. Overview photo of the well pad taken from the northern edge looking south. Note: reclaimed well falls within a corner crop section. Minimal vegetation observed because of snow cover, will have to re-inspect in summer 2022.