

Final Reclamation Inspection

January 17th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 328363

Inspection Document #: 701900344

SWSW Section 21 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Elder 13-21
Location ID: 328363



Photo 1. 2021 aerial imagery of the well pad and the tank battery (north is up). Note: The tank battery and well pad shared a disturbance pad and falls within the Rangeview Ranches subdivision.

Inspection Photos
Location Name: Elder 13-21
Location ID: 328363



Photo 2. Overview photo of the well pad and the tank battery.