

# Final Reclamation Inspection

February 15, 2022

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 439738

Inspection Document #: 697503746

Weld County, CO

SWSE Section 31 T7N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 1.** Photo taken from the southern location, facing North. Photo illustrates the Operator performed the previous corrective to conduct additional final reclamation activities. Location will remain in-process as the location is not reflective of reference area vegetation.



Inspection Photos  
Location Name: Bobcat #O-K-31HNB  
Location ID: 439738



**Photo 2.** Photo taken from the southwestern location, facing North. Photo illustrates reference area vegetation outside of the red-dashed line.

