

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Photo 3 Pump Jack

Photo 4 Gas Engine

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Photo 5 TB sign



Photo 6 TB

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Photo 7 Open top tank has about 1 ft. of sludge in it covered with chicken wire



Photo 8 Vertical separator

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Photo 9 ECD