

Inspection Photos

Location Name: UPRR 60 PAN AM A 1

Location ID: 319680



Pic 1 wellhead before LOTO



Pic 2 wellhead after LOTO, master valve is seized in position, appears open, but sales line appears to be shut. Casing valves are in close position,

Inspection Photos

Location Name: UPRR 60 PAN AM A 1

Location ID: 319680

Feb 28, 2022 at 11:56:43 AM
39.976515,-104.591567
Adams County
COGCC



Pic 3 Separator and electric equipment. Unable to access separator due to weed growth on location

Feb 28, 2022 at 11:57:11 AM
39.976423,-104.591560
Adams County
COGCC



Pic 4 gas meter run



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: UPRR 60 PAN AM A 1

Location ID: 319680



Pic 5 tanks, unable to access tanks to see if there is fluid in them due to weed growth on location



Pic 6 battery sign

