

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:

Type	#	corrective date
Type: Deadman # & Marked	# 6	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	

Comment: appears plumbed to surface		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: automation		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: gas engine		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV CONCRETE		
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	60 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: shares containment with crude tank				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.924580,-104.546220
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Wells Served By Facilities Above

AirsID

API Number

API Number

AirsID

001-07626

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202221 Type: WELL API Number: 001-07626 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/19/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

