

# Inspection Photos

API: 071-06903

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/28/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 2/28/2022

## Inspection Photos



**Photo 1.** Facing back east along the main road traveling to the well site. This area of the road side has been repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 2/28/2022

## Inspection Photos



**Photo 2.** Facing southwest along the main road traveling to the well site. There area has been repaired and was in process of being seeded. There was also work being conducted further along the road.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 2/28/2022

## Inspection Photos



**Photo 3.** Facing south along the access road. There is erosion along the road that needs to be repaired and stabilized. This area has not yet been repaired



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 2/28/2022

## Inspection Photos



**Photo 4.** Facing south at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 2/28/2022