

Construction and Stormwater Inspection

February 25, 2022

Operator: BURLINGTON RESOURCES OIL & GAS LP - 26580

Location ID: 474845

Inspection Document #: 697503748

Weld County, CO

NESE Section 17 T4S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EASTERN HILLS 4-65 17-18 /3AH
Location ID: 474845



Photo 1. Photo taken from the entrance of location, facing North. Photo illustrates a mailbox with the approved forms to comply with Rule 406.c.



Inspection Photos
Location Name: EASTERN HILLS 4-65 17-18
/3AH
Location ID: 474845



Photo 2. Photo taken from the entrance of location, facing West. Photo illustrates a ditch BMP that has been installed around the entire perimeter of location, which is directed to a stabilized outlet. Culverts are in process of being installed.



Photo 3. Photo taken from the entrance of location, facing East. See comments under Photo 2.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503748

Inspection Photos
Location Name: EASTERN HILLS 4-65 17-18
/3AH
Location ID: 474845



Photo 4. Photo taken from the northeastern location, facing East. See comments under Photo 2.



Photo 5. Photo taken from the northeastern location, facing South. See comments under Photo 2.



Inspection Photos
Location Name: EASTERN HILLS 4-65 17-18
/3AH
Location ID: 474845



Photo 6. Photo taken from the northeastern location, facing West. Photo illustrates the topsoil stockpile along the western location.



Photo 7. Photo taken from the northwestern location, facing West. Photo illustrates the sediment basin that has been engineered for a one hour, 100-year storm event.



Inspection Photos
Location Name: EASTERN HILLS 4-65 17-18 /3AH
Location ID: 474845



Photo 8. Photo taken from the northwestern location, facing South. See comments under Photo 2.