

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2022

Submitted Date:

02/23/2022

Document Number:

700600364**FIELD INSPECTION FORM**Loc ID 324797 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	<a href="#">All Inspections</a>
Pike, Jeremy		jpike@entradainc.com	
Hart, Dale	719-688-1638	dale@westernoperating.com	

**General Comment:**

This is an environmental inspection to document status of spill clean up. See attached photos.

Please see approved spill report and conditions of approval for guidance.

If significant modifications to the tank battery and containment are needed then the battery would need to comply with Rule 603.o. which requires lined containment.

The landowner has water wells near the spill area. One is screened at 30' so due to the potential for shallow groundwater samples from his wells will need to be obtained.

**Environmental****Spills/Releases:**

Type of Spill: OIL \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Spill of produced water and oil has flowed into active remediation area.Corrective Action: Update Remediation 20712 to reflect clean up of new spill. Clean up of this spill will occur under Remediation 20712

Date: 03/04/2022

Reportable: YES \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402963733	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671821">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671821</a>
700600365	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5671819</a>