

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



Photo #6840 from entrance to location.



Photo #6049 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



Photo #6050 Location lacks stabilization.



Photo #5751 from inspection #699804041 conducted on 1/21/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



Photo #6150 location lacks stabilization.



Photo #5753 from inspection #699804041 conducted on 1/21/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



Photo #6052 Insufficient tracking controls at entrance to location.