

Inspection Photos
Location Name: Razor 14-1143H
Location ID: 430061



Photo 1 – Rig Sign at Entrance



Photo 2 – Location Signs at Entrance



Inspection Photos
Location Name: Razor 14-1143H
Location ID: 430061



Photo 3 – Workover Rig in process of MIRU



Photo 4 – Stained Soil at Exhaust