

# Final Reclamation Inspection

February 25, 2022

Operator: TRANS TEXAS ENERGY INC. - #89161

Location ID: 377994

Inspection Document #: 697503756

Arapahoe County, CO

NESE Section 8 T5S R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MURPHY #1-8  
Location ID: 377994



**Photo 1.** Photo taken from the well location, facing West. Photo illustrates all equipment has been removed. It appears smooth brome was initially seeded and now blue grama is starting to replace the smooth brome.