

Inspection Photos
Location Name: Wanda 41-8 & Penny 32-8
Location ID: 320082



Pic 1 Penny 32-8 Master valve is in the closed position, all ball valves on flowlines, and casing are in close position. Bradenhead valve is in closed position.

Pic 2 Wanda 41-8 Master valve is in the close position, all ball valves are in closed position. Bradenhead valve is in close position.

Inspection Photos
Location Name: Wanda 41-8 & Penny 32-8
Location ID: 320082

Mar 1, 2022 at 1:34:03 PM
39.982758,-104.565763
Adams County
COGCC



Pic 3 Tanks and battery sign


Mar 1, 2022 at 1:35:09 PM
39.982758,-104.565763
Adams County
COGCC



Pic 4 tanks

Inspection Photos
Location Name: Wanda 41-8 & Penny 32-8
Location ID: 320082

Mar 1, 2022 at 1:35:22 PM
39.982758,-104.565763
Adams County
COGCC



Pic 5 Gas meter runs

Mar 1, 2022 at 1:35:37 PM
39.982861,-104.565767
Adams County
COGCC



Pic 6 Separators.