

Interim Reclamation Inspection

February 25, 2022

Operator: RENEGADE OIL & GAS COMPANY LLC - #74165

Location ID: 320644

Inspection Document #: 697503759

Arapahoe County, CO

SWSW Section 25 T5S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lowry State #13-25
Location ID: 320644



Photo 1. Google Earth aerial imagery from 6/10/2021 illustrating stormwater repair work and equipment removal work that needs to be seeded (red polygons).



Inspection Photos
Location Name: Lowry State #13-25
Location ID: 320644



Photo 2. Photo taken from the eastern tank battery, facing East. Photo illustrates Operator has performed additional stormwater repair work but has not seeded the area. Some rill erosion was observed (red arrow) and should be repaired when performing seedbed prep.



Inspection Photos
Location Name: Lowry State #13-25
Location ID: 320644



Photo 3. Photo taken from the eastern tank battery, facing East. See comments under Photo 2.

Inspection Photos
Location Name: Lowry State #13-25
Location ID: 320644



Photo 4. Photo taken from the southern tank battery, facing Southwest. Photo illustrates Operator has removed unused risers and the area needs to be seeded.

