

## Inspection Photos

Location Name: CAERUS PICEANCE LLC MURRAY-68S96W /1SESW

Location ID: 334086



Photo #6070 from entrance to location.



Photo #6071 from entrance to location.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC MURRAY-68S96W /1SESW

Location ID: 334086



**Photo #6072** Insufficient tracking BMP at entrance to location



**Photo #6073** Sediment has been transported on to County road 306.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC MURRAY-68S96W /1SESW

Location ID: 334086



**Photo #6074** Sediment has been transported on to County road 306 for approximately 100 yards.



**Photo #6075** Sediment has been transported on to County road 306 for approximately 100 yards.