

COLORADO OI



99999999

# REGISTRATION COMMISSION FIELD INSPECTION REPORT

JAN. 07 1998

C

☐ NOTICE OF UNSATISFACTORY INSPECTION

☒ NOTICE OF SATISFACTORY INSPECTION

 1120 Lincoln Street, Suite 801  
 Denver, CO 80203  
 (303)894-2100

API No. 05- (017 -07386)

LEASE NAME: BLEDSOE #7-12

LOCATION: SWNE12-12S-51W

OPERATOR: UPR

DATE: 12-22-97

INSPECTOR: R. VanSickle

Insp. Type: PR

Insp. Status: PR

PA: Y

(N)

Pass/Fail: P

F

Viol.: Y

(N)

NOV: Y

(N)

## INSPECTION ITEM

## COMMENTS

## INPUT

<b>Well ID Signs</b> (Rule 210, 604.c(4))	✓	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	None	✓
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)	Around well & battery	
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)	Pmpg unit, 4 400's, vert. H-T, 300 BBL FRP water tank -	✓
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)	OK	
<b>General Housekeeping</b> (Rule 603)	OK	
<b>Spills (Oil/Water)</b> (Rule 907)	None	
<b>Bradenhead</b> (Rule 207.b)	—	
<b>Drilling Well/Workover</b> (Rule 317)	—	
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	—	
<b>Miscellaneous</b>	—	

MAR 12 1998

CORRECTIVE ACTION REQUIRED: None.

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00494818

White - File Canary - Operator Pink - Well Site