

Inspection Photos

API: 071-08719

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/2/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08719 | Date: 3/2/2022

Inspection Photos



Photo 1. Facing northeast toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08719 | Date: 3/2/2022

Inspection Photos



Photo 2. Facing north toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08719 | Date: 3/2/2022

Inspection Photos



Photo 3. Facing toward the pit. The pit liner is torn and degraded. The fence around the pit is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08719 | Date: 3/2/2022