

Caerus Piceance LLC
B9E
Location # 334833



Location



location/ lack of battery signage



**Caerus Piceance LLC
B9E
Location # 334833**



Location



Lack of stabilization/compaction



Caerus Piceance LLC
B9E
Location # 334833



Lack of stabilization/compaction



Access road



Caerus Piceance LLC
B9E
Location # 334833



Lack of bird protector



Bird protector



Caerus Piceance LLC
B9E
Location # 334833



Open exhaust thaw lines



Open exhaust thaw lines



Caerus Piceance LLC
B9E
Location # 334833



Staining



Staining

Caerus Piceance LLC
B9E
Location # 334833



Staining



Staining

Caerus Piceance LLC
B9E
Location # 334833



Staining



Staining

Caerus Piceance LLC
B9E
Location # 334833



Load line



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources