

Inspection Photos
Musick-McClintock #5
Spill ID: 481685



Photo 1 – West wall of open excavation; impacts remain in-situ.



Photo 2 – North wall of open excavation; impacts remain in-situ.

Inspection Photos
Musick-McClintock #5
Spill ID: 481685



Colorado Oil and Gas Conservation Commission
40.27581, -104.69416, 4832.7ft, 48°
03/02/2022 10:16:47 AM

Photo 3 – East wall of open excavation.



Colorado Oil and Gas Conservation Commission
40.27576, -104.69419, 4827.2ft, 14°
03/02/2022 10:16:28 AM

Photo 4 – Surface area of scraped soil.

**Inspection Photos
Musick-McClintock #5
Spill ID: 481685**



Photo 5 – Staging area for any soils stored on site. Area is underlined by a plastic liner with appropriate signage.



Photo 6 – Staging area for any soils stored on site.