

## Inspection Photos

Location Name: UPRR-BESSIE 1

Location ID: 320144

Mar 3, 2022 at 11:07:18 AM  
39.965463,-104.565524  
Adams County  
COGCC



Mar 3, 2022 at 11:08:47 AM  
39.965554,-104.565586  
Adams County  
COGCC



**Pic 1 tank, weeds are unmanaged on location.**

**Pic 2 Separator, weeds unmanaged on location**

## Inspection Photos

Location Name: UPRR-BESSIE 1

Location ID: 320144



**Pic 3 wellhead, master valve and flowline valves were in the close position at time of inspection.**



**Pic 4 During inspection it was discovered that the wellhead was leaking gas out of the top of gauge pictured. Ball valve is seized in the slight open position, needle valve was open and shut during inspection. Needle valve is damaged and still has a slight leak of gas.**