

Inspection Photos

Location Name: State Horth 13-16 & State Horth 22-16

Location ID: 320045

Mar 3, 2022 at 12:24:26 PM
39.965626,-104.558524
Adams County
COGCC



Mar 3, 2022 at 12:59:19 PM
39.962150,-104.562949
Adams County
COGCC



Pic 1 State Horth 22-16. At time of inspection master valve, and flow lines were in the open position. During inspection master valve and flowline valves were put in the close position.

State Horth 13-16. At time of inspection casing valves and master valve were in the open position. During inspection master valve, and

Mar 3, 2022 at 12:40:26 PM
39.958736,-104.565144
Adams County
COGCC



Pic 3 Tanks, weeds unmanaged on location, at time of inspection unable to access tanks due to weed growth on location .

Mar 3, 2022 at 12:41:08 PM
39.958735,-104.565144
Adams County
COGCC



Pic 4 trash, and weeds on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Mar 3, 2022 at 12:41:23 PM
39.958833,-104.565148
Adams County
COGCC



**Pic 5 separator, ECD, abandoned gas meter
run. Trash on location.**