

Inspection Photos
Location Name: Eleanor Arnold B 1
Location ID: 320084



Pic 1 wellhead, At time of inspection master valve, flowline valves, and casing valves were in close position. 1 casing valve appears to be seized in the open position. Bradenhead valve is closed.



Pic 2 gas meter run, weeds

Inspection Photos

Location Name: Eleanor Arnold B 1

Location ID: 320084

Mar 3, 2022 at 2:29:29 PM
39.977377,-104.537162
Adams County
COGCC



Pic 3 separator, weeds

Mar 3, 2022 at 2:30:24 PM
39.977452,-104.537217
Adams County
COGCC



Pic 4 produced water open top tank, fluid present in tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Eleanor Arnold B 1

Location ID: 320084



Pic 5 oil tank appears to be empty.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources