

**Inspection Photos**  
**Operator: Morningstar Operating**  
**API: 007-06184**  
**Date: 2/28/2022**



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is largely dormant/grazed at this time. Observed perennial grasses include crested wheatgrass and sand dropseed.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area vegetation comprised of open grass field, cattle present and grazed/dormant at this time.