

Inspection Photos

03/02/2022

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312741

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312741



March 2, 2022
39.22616872N 108.19181383W



March 2, 2022
39.22613931N 108.19189309W

Photo 1: Photos taken from the south end of the Location. Photos 1-2 provide an overview of the Location from northwest, north, northeast to southeast. Photos show that final reclamation of the Location (recontouring/regrading/revegetation) has not been performed in accordance with 1004 rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312741



March 2, 2022
39.22615072N 108.19193196W



March 2, 2022
39.22613519N 108.19194067W

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312741



Photo 3: Photos taken from the two Location entrances on the south end of the Location. Photos show gravel/road base remaining on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312741



Photo 4: Photo taken from the east end of the Location, facing northwest. Photo shows areas of the Location where subsidence issues are evident or a pit remains.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312741



Photo 5: Photo taken from the east end of the Location facing north. Photo an example showing slopes of the Location have not been recontoured/reclaimed; cut/fill slopes remain evident.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312741



March 2, 2022
39.22641313N 108.19242737W

Photo 6: Photo shows example of noxious knapweed debris observed of the Location; vegetation evident on the Location is predominantly undesirable plant species, including Russian thistle.