

Inspection Photos

03/02/2022

Operator: GORDON ENGINEERING INC -
34720

Location ID: 312560
Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312560



Photo 1: Photo taken from the access road, facing east. Photo taken from the access road. Photo example showing access road has not been recontoured/regraded/reclaimed in accordance with 1004 rules.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312560



Photo 2: Photo taken from the access road. Photo shows Operator has “pot-holed” the access road. Soil piles resulting from this operation have been left loose and unstabilized, and is considered a pollutant source; sediment transport and erosion from the soil piles evident.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312560



Photo 3: Continued from photo 2. Photo shows Operator has “pot-holed” the access road. Photos show sediment transport and deposition observed to do unstabilized soils at access road.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312560



March 2, 2022
39.22682374N 108.23922217W



March 2, 2022
39.22682228N 108.2392213W

Photo 4: Photos taken from the west end of the Location facing northwest and east. Photos show Location has not been recontoured/regraded or reclaimed in accordance with 1004 Rules.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312560



Photo 5: Photo taken from the northwest end of the Location. Photo provides example showing fill slopes; Location has not been recontoured/regraded and reclaimed in accordance with 1004 rules.