

Inspection Photos
Operator: Simcoe
API: 007-05179
Date: 2/28/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses similar to the reference area (irrigated grass field).



Photo 3. View of reference area comprised of irrigated grassland with grasses and wetland species such as timothy, tall fescue, and cattails.