

# Inspection Photos

03/02/2022

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 312422

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 312422



**Photo 1:** Photo left taken from the north end of the Location, facing south. Photo shows vegetative establishment on the north end of the Location appears to be progressing towards 1004 standards.

Photo right taken from the south end of the Location, facing northeast. Photo shows areas of the Location where desirable vegetative establishment was not evident; limited visibility due to snow cover prevent an accurate assessment of the reclamation, however these areas may require additional reclamation in order to meet 1004 standards. A followup inspection be conducted to determine compliance with 1004 Rules.