

Inspection Photos
Location Name: MILLER-66N64W /29SESE
Location #: 323297




Photo #1
Miller 16-29 (05-123-12830) Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Intermediate plugs cementing



Photo #2
Miller 16-29 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Site safety signage

Inspection Photos

Location Name: MILLER-66N64W /29SESE

Location #: 323297



Photo #3

Miller 16-29 Wellsite

Plugged & Abandoned | PA

Plugging Operations: Cementing | WK

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources