

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402974906

Date Received:
03/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 952 ECHO LANE SUITE 480

City: HOUSTON State: TX Zip: 77024

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rikki Ross

405-921-1825

rikki@d90energy.com

David Boyer

303-994-0000

david@d90energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689805592

Inspection Date: 03/30/2021

FIR Submit Date: 04/14/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC

Company Number: 10598

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 451456

Location Name: Refuge Number: 0780 S16 County: _____

Qtrqr: NENE Sec: 16 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.583981 Longitude: -106.369379

FACILITY - API Number: 05-057- -00 Facility ID: 451456

Facility Name: Refuge Number: 0780 S16

Qtrqr: NENE Sec: 16 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.583981 Longitude: -106.369379

CORRECTIVE ACTIONS:

1 CA# 149464

Corrective Action: Install sign to comply with Rule 605.d.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 01/05/2022

Operator
Comment:

D90 Energy is operator of record as of 1/5/22. Signage is accurate and complete.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 149465

Corrective Action: Install sign to comply with Rule 605.e.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 01/05/2022

Operator
Comment: D90 Energy is operator of record as of 1/5/22. Signage is accurate and complete.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 149466

Corrective Action: Install sign to comply with Rule 605.g.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 01/05/2022

Operator
Comment: D90 Energy is operator of record as of 1/5/22. Signage is accurate and complete.

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 149850

Corrective Action: Well must be either:

Date: 05/12/2021

1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or

2) Be properly plugged and abandoned.

3) A sundry requesting continued temporarily abandoned status should be submitted to COGCC engineering within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Response: CA COMPLETED

Date of Completion: 10/11/2021

Operator
Comment: Well plugged and abandoned 10/11/2021. Form 6 is attached.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Signage is accurate and complete. Form 4 is attached showing temporarily abandoned status in May 2021. Form 6 is attached showing well plugged and abandoned on 10/11/2021.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: _____

Title: Regulatory Analyst

Date: 3/7/2022 10:37:23 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402974917	Form 4
402974918	Form 6

Total Attach: 2 Files