

Inspection Photos

API: 071-06908

Operator: OGRIS OPERATING LLC

Inspection Date: 3/4/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06908 | Date: 3/4/2022

Inspection Photos



Photo 1. Facing southeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06908 | Date: 3/4/2022

Inspection Photos



Photo 2. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06908 | Date: 3/4/2022

Inspection Photos



Photo 3. The vegetation is well established at the location. The well signs are posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06908 | Date: 3/4/2022