

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402354343

Date Received:

03/27/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Michael Hannigan</u>	<u>970-882-5532</u>	<u>michael_hannigan@kindermorgan.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800680  
Inspection Date: 02/20/2020 FIR Submit Date: 02/24/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP Company Number: 46685  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 313490

Location Name: MCELMO DOME UNIT 23-37-18-N37N18W Number: 23SWSW County: MONTEZUMA  
Qtrqtr: SWS Sec: 23 Twp: 37N Range: 18W Meridian: N  
Latitude: 37.444937 Longitude: -108.810061

FACILITY - API Number: 05-083-00 Facility ID: 224224

Facility Name: MCELMO DOME UNIT 23-37-18 Number: YB-2  
Qtrqtr: SWS Sec: 23 Twp: 37N Range: 18W Meridian: N  
Latitude: 37.444937 Longitude: -108.810061

CORRECTIVE ACTIONS:

1 ☒ CA# 136689

Corrective Action: Contact COGCC EPS staff regarding Rule 906.c. Date: 02/26/2020

Response: CA COMPLETED Date of Completion: 02/28/2020

Operator Comment: Kinder Morgan EHS Supervisor Mike Hannigan contacted COGCC Environmental Protection Specialist Jim Hughes via telephone on 2/28/2020 to discuss the applicability of Rule 906.c. to the interim reclamation area of the YB-2 well location. Jim's preference is to address the issue through the FIRR process rather than through a Site Remediation Workplan (Form 27). Soil samples will be collected and analyzed for EC, SAR and pH to

determine level of impact and which soil amendments are required for remediation and successful reclamation of the area of the YB-2 location noted in the FIR. Initial soil samples have been collected and soil amendments have been ordered. Additional soil sample collection and laboratory analysis will take place when weather conditions allow.

COGCC Decision: Approved pending re-inspection

COGCC Representative: If soil sampling reveals impacts related to oil and gas activities at this site, a Form 27 Site Investigation and Remediation Workplan shall be submitted by the operator.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Hannigan

Signed: \_\_\_\_\_

Title: EHS Supervisor

Date: 3/27/2020 10:32:19 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402354343	FIR RESOLUTION FORM
402363365	FIR RESOLUTION SUBMITTED

Total Attach: 2 Files