

Final Reclamation Inspection

February 28, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 305138

Inspection Document #: 697503773

Weld County, CO

NWSE Section 7 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. COGCC GISOnline 2019 aerial imagery during active operations. Photo illustrates the well location, access road and associated tank battery.

Inspection Photos
Location Name: HICKS P #7-23
Location ID: 305138



Photo 2. Photo taken east of the associated tank battery, facing West. Photo illustrates all equipment has been removed from the tank battery and well location. It appears gravel has been removed and the location has been contoured. The crop field is currently fallow.