

Final Reclamation Inspection

February 28, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 331906

Inspection Document #: 697503780

Weld County, CO

NWNW Section 7 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HICKS #4-7
Location ID: 331906



Photo 1. COGCC GISOnline 2019 aerial imagery during active operations. Photo illustrates the well location, access road and associated tank battery.



Inspection Photos
Location Name: HICKS #4-7
Location ID: 331906



Photo 2. Photo taken from the associated tank battery, facing South. Photo illustrates all equipment has been removed from the tank battery and well location. It appears gravel has been removed and the location has been contoured. The crop field is currently fallow.



Inspection Photos
Location Name: HICKS #4-7
Location ID: 331906



Photo 3. Photo taken north of the well location, facing South. See comments under Photo 2.

