Final Reclamation Inspection

February 28, 2022

Operator: PDC ENERGY INC - 69175
Location ID: 322829
Inspection Document #: 697503786
Weld County, CO
SESE Section 6 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 1. Photo taken south of the location, facing North. Photo illustrates Operator has performed final reclamation activities.

Photo 2. Photo taken from the associated offsite tank battery, facing North. Photo illustrates tank battery is still in use for other nearby wells.