

**Inspection Photos**  
**Location Name: Shively Battery**  
**Location ID: 320055**

Mar 7, 2022 at 4:27:32 PM  
39.983055,-104.506434  
Adams County  
COGCC



**Pic 1 Shively 11-12 wellhead. At time of inspection all valves were in the close position. During inspection well was LOTO.**

Mar 7, 2022 at 4:36:18 PM  
39.983032,-104.501620  
Adams County  
COGCC



**Pic 2 Shively 21-12. At time of inspection all valves were in the close position. During inspection it was observed that gas was leaking out of packing, and Master valve. Valve is in the close position, and will not properly seal. Attempted to tighten hammer union with hammer and would not tighten.**





## Inspection Photos

Location Name: Shively Battery

Location ID: 320055

Mar 7, 2022 at 4:41:26 PM  
39.984659,-104.500015  
Adams County  
COGCC



**Pic 3 ECD, Separators. Separator house is in disrepair and needs to be removed.**

Mar 7, 2022 at 4:41:54 PM  
39.984620,-104.500145  
Adams County  
COGCC



**Pic 4 gas meter run, trash on location.**

## Inspection Photos

Location Name: Shively Battery

Location ID: 320055



**Pic 5 Tanks. At time of inspection tanks appeared to be empty.**