

**RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092**



Tank battery doesn't meet Rule 605.e..



Base of berm is marshy.

**RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092**



Damaged tank labels.



Damaged tank labels.

**RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092**



No API # on well sign.

RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092



**RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092**



Load line spill pan needs maintained.

**RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092**



Subsidence of tank ground base. Base of berm is marshy.



Sediment coming off hillside behind tank battery berm and collecting sediment and stormwater in berm.

**RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092**



**Sediment coming off hillside behind tank battery berm
and collecting sediment and stormwater in berm.**

**RIO MESA RESOURCES INC
GOVERNMENT-61N102W 1SW SW
Location # 315092**



**Storm water damage of access road and moving
across south end of location.**