

Inspection Photos
Location Name: Horsetail 07H PAD
Location ID: 442408




Photo 1 – Signs at Entrance

Photo 2 – 1816 missing Wellhead Sign

Inspection Photos
Location Name: Horsetail 07H PAD
Location ID: 442408



Photo 3 – 1815 Wellhead missing Sign

Photo 4 – Gas Lift Injection Meter Shed

Inspection Photos
Location Name: Horsetail 07H PAD
Location ID: 442408



Photo 5 – Gas Lift Injection Meter Sheds