

Inspection Photos
Location Name: Horsetail 07G PAD
Location ID: 443049



Photo 1 – Signs at Entrance

Photo 2 – North Wellheads

Inspection Photos
Location Name: Horsetail 07G PAD
Location ID: 443049



Photo 3 – 1810 Wellhead missing Sign

Photo 4 – 0642 Wellhead missing Sign

Inspection Photos
Location Name: Horsetail 07G PAD
Location ID: 443049



Photo 5 – Gas Lift Injection Meter Shed

Photo 6 – Gas Lift Injection Meter Shed

Inspection Photos
Location Name: Horsetail 07G PAD
Location ID: 443049



Photo 7 – Debris on Location